

# Operating Instructions

## Ss Brewtech LCD Thermometer

### INSTRUCTIONS:

- Open the battery cover and insert two LR44 batteries
- The display is always on when batteries inserted
- Remove batteries for long periods of inoperation
- LCD will display "H" if over max temp spec (154F)
- LCD will display "L" if under min temp spec (-54 F)

### FEATURES:

- LCD display
- Two batteries for longer operating time
- Designed for use with InfuSsion™ Mash Tun

### SPECIFICATIONS:

- Storage temps: -20 F to 180 F
- Operating temps: 0 F to 180 F
- Operating humidity: 5% to 80%
- Accuracy: +/- 1 F
- Batteries: LR44 / 1.5V



©Copyright Ss Brewing Technologies 2014

# Operating Instructions

## Ss Brewtech LCD Thermometer

### INSTRUCTIONS:

- Open the battery cover and insert two LR44 batteries
- The display is always on when batteries inserted
- Remove batteries for long periods of inoperation
- LCD will display "H" if over max temp spec (154F)
- LCD will display "L" if under min temp spec (-54 F)

### FEATURES:

- LCD display
- Two batteries for longer operating time
- Designed for use with InfuSsion™ Mash Tun

### SPECIFICATIONS:

- Storage temps: -20 F to 180 F
- Operating temps: 0 F to 180 F
- Operating humidity: 5% to 80%
- Accuracy: +/- 1 F
- Batteries: LR44 / 1.5V



©Copyright Ss Brewing Technologies 2014

# Operating Instructions

## Ss Brewtech LCD Thermometer

### INSTRUCTIONS:


- Open the battery cover and insert two LR44 batteries
- The display is always on when batteries inserted
- Remove batteries for long periods of inoperation
- LCD will display "H" if over max temp spec (154F)
- LCD will display "L" if under min temp spec (-54 F)

### FEATURES:

- LCD display
- Two batteries for longer operating time
- Designed for use with InfuSsion™ Mash Tun

### SPECIFICATIONS:

- Storage temps: -20 F to 180 F
- Operating temps: 0 F to 180 F
- Operating humidity: 5% to 80%
- Accuracy: +/- 1 F
- Batteries: LR44 / 1.5V



©Copyright Ss Brewing Technologies 2014

# Operating Instructions

## Ss Brewtech LCD Thermometer

### INSTRUCTIONS:

- Open the battery cover and insert two LR44 batteries
- The display is always on when batteries inserted
- Remove batteries for long periods of inoperation
- LCD will display "H" if over max temp spec (154F)
- LCD will display "L" if under min temp spec (-54 F)

### FEATURES:

- LCD display
- Two batteries for longer operating time
- Designed for use with InfuSsion™ Mash Tun

### SPECIFICATIONS:

- Storage temps: -20 F to 180 F
- Operating temps: 0 F to 180 F
- Operating humidity: 5% to 80%
- Accuracy: +/- 1 F
- Batteries: LR44 / 1.5V



©Copyright Ss Brewing Technologies 2014